


ご使用前に必ず本書をお読みいただき、ご使用される方がいつでも見ることができる場所に必ず保管してください。


各部の名称



回転速度12,000min⁻¹以上でご使用の場合、カッタをアーバに取り付けた状態でのバランス調整を **BIG** にご依頼ください。

インサートの取り付け方

1. インサートセット前にインサート座面にエアを吹き付け、異物を取り除いてください。
2. レンチ (2mm 六角レンチ等) の先端をリフトナットの穴に差し込み、リフトナットを反時計回りに回し、リフトスクリューをインサート座面より少しだけ下げてください。



⚠ ご注意

リフトスクリューを下げすぎると、リフトナットの穴にレンチの先端が挿入できなくなることがありますので、ご注意ください。


3. インサートの背面、側面をウエス等で丁寧に拭いてください。
4. インサートをインサート座面に軽く押し付けながら、クランプスクリューを推奨締め付けトルク1.0N・mで締め付けてください。
5. インサート座面にすきまが無いことをご確認ください。

⚠ ご注意

- ・ 付属または純正のクランプスクリュー以外は使用しないでください。
- ・ インサート交換時は刃先で手を切らないよう注意してください。
- ・ インサートクランプスクリューとレンチは消耗品ですので定期的に交換してください。
- ・ 先端の傷んだレンチ、穴の傷んだスクリューは使用しないでください。

刃先の調整方法

1. プリセッタ上で最も刃先高さの高いインサートを見つけてください。
2. 最も高いインサートのリフトナット・スクリュにテンションを与え固定するために、リフトナットを時計回りに回し、インサートを少し持ち上げます。
3. 目安としては刃先が5 μm ほど持ち上がる程度です。
2.の刃先高さを目標に他のインサートも同じ高さに揃えていきます。
そして全ての刃先高さが2 μm 以内に入るようにします。



⚠ ご注意

刃先にプリセッタのスタイラスを急速に強い力で接触させると刃先が欠損する恐れがあるため、軽くゆっくり接触させてください。また、スタイラスが刃先に接触している時にカット本体を動かすと、刃先が欠損する恐れがあるため、接触中は絶対に動かさないでください。

切削に関して

- ・標準切削条件は、総合カタログをご参照ください。
- ・鋳鉄を加工する場合、ウェット加工では熱亀裂の進行が早くインサート欠損につながりますのでドライ加工でご使用ください。
アルミニウムを加工する場合、溶着を防ぎ良い仕上げ面を得るために水溶性切削油剤の使用をお奨めします。
- ・フェイスミルアーバには、センタスルー対応で高精度な **(BIG)** FMH型アーバを推奨します。
- ・最高許容回転速度以上での使用は絶対にしないでください。

カット径	最高許容回転速度
$\phi 50$ 、 $\phi 63$	20,000min ⁻¹
$\phi 80$	16,000min ⁻¹
$\phi 100$	12,800min ⁻¹
$\phi 125$	10,200min ⁻¹
$\phi 160$	8,000min ⁻¹

⚠ ご注意

- ・刃数を減らしての加工や、突出しの大きいアーバを使用する場合、バランス調整をせずに高速回転でカットを使用しないでください。
- ・不適切な切削条件での加工は行わないでください。
- ・剛性、馬力の十分な機械でご使用ください。
- ・ぶつけるなど、本体に強い衝撃を与えた後は使用しないでください。
- ・工具は切削時高温になります。使用直後に直接手で触れると火傷の危険があります。
- ・切りくずの飛散や誤った使用による工具の破損に対して、機械のカバーや安全めがねなどの保護具をご使用ください。
- ・不水溶性切削油剤は火災発生の危険性がありますので使用しないでください。

スペアパーツ

インサート型式	リフトスクリュセット (リフトスクリュ1個) (リフトナット1個)	インサートクランプスクリュセット (スクリュ10個) (専用レンチ1本)	ドライバー型 レンチ
PL0705...	LSN35	S2506DS	DA-T8


インサートの選定については、総合カタログをご参照ください。

Please read these instructions before use and keep them where the operator may refer to them whenever necessary.

OPERATION MANUAL
DOWNLOAD SITE
[https://big-daishowa.com/
manual_index.php](https://big-daishowa.com/manual_index.php)




NAMES OF PARTS



When a cutter is used at a higher rotational speed than $12,000\text{min}^{-1}$, request **BIG** to balance the cutter attached to a toolholder.

HOW TO ATTACH INSERTS

1. Before attaching inserts, remove any foreign particles on insert seats with compressed air.
2. Put the tip of a wrench (2mm Allen key) into the hole on the lifting nut. Turn the lifting nut counterclockwise and lower it slightly from the insert seat.



CAUTION

If the lifting screw is lowered too far, the tip of the wrench cannot be put into the hole of the lifting nut.


3. Wipe the side and back faces of the inserts thoroughly.
4. Tighten the screw with a tightening torque of $1.0\text{N}\cdot\text{m}$ while lightly pressing the insert into its seat.
5. Make sure that there is no gap between the insert and the insert seat.

CAUTION

- Do not use other insert clamping screws than the original or genuine new ones.
- When exchanging an insert, be careful not to cut your hands with its edges.
- Periodically replace insert clamping screws and wrenches that are consumable.
- Do not use any wrenches or clamping screws that are damaged on their tips or holes.

HOW TO ADJUST HEIGHT OF INSERTS

1. Find the insert with the highest cutting edge on a presetter.
2. To set the lifting screw and nut of the first insert, turn the lifting nut clockwise and lift the insert slightly (about 5 μ m).
3. Lift other inserts to the same height as the insert set in (2).
The height of all the inserts should be within 2 μ m.



CAUTION

If the stylus of a presetter is strongly and rapidly touching a cutting edge, the cutting edge may chip. A stylus must touch the cutting edge lightly and slowly. If the cutter is moved while the stylus is touching a cutting edge, the cutting edge may chip. Do not move the cutter while the stylus touches a cutting edge.

ABOUT CUTTING CONDITION

- Refer to the General Catalog for recommended cutting conditions.
- If coolant is used in machining cast iron, thermal cracking on the cutting edges tends to progress quickly. Dry cutting is recommended for cast iron. In case of machining aluminum, usage of coolant is recommended to prevent built-up edge for better surface finish.
- **BIG** FMH face mill arbors with high accuracy and a center through coolant holes are recommended.
- Do not exceed the allowable maximum rotational speed.

Cutter dia.	The allowable max. speed
ø50, ø63	20,000min ⁻¹
ø80	16,000min ⁻¹
ø100	12,800min ⁻¹
ø125	10,200min ⁻¹
ø160	8,000min ⁻¹

CAUTION

- In high rotational speed, do not use a cutter with less inserts or long projection lengths without balancing.
- Do not apply inappropriate cutting conditions.
- Do not use any cutters that have collided and suffered a strong impact.
- Use machine tools with sufficient rigidity and horsepower.
- A cutter becomes very hot during cutting. Touching a cutter directly by hand soon after cutting will lead to severe burns.
- To prevent chips and broken tools from scattering, install a safety cover on a machine tool and use safety glasses.
- Do not use insoluble oil that may cause fire.

SPARE PARTS

Insert	Lifting screw set (1pc of lifting screw) (1pc of lifting nut)	Insert clamping screw set (10pcs of screws) (1pc of wrench)	Wrench
PL0705...	LSN35	S2506DS	DA-T8

Refer to the catalogue of "SPEED FINISHER" for insert selections.